Release Notes: GCC 4.9.2.201701-GNURL78

1st of April, 2017

CyberThor Studios Ltd. is releasing the GCC 4.9.2.201701-GNURL78, a cross compiler tool for Renesas RL78 micro-controllers.

SALIENT FEATURES

The GCC 4.9.2.201701-GNURL78 toolchain is based on:

- ❖ GCC 4.9.2 [released]
- ❖ Binutils 2.24 [released]
- Newlib 2.1.0 [released]
- ❖ GDB 7.8.2 [released]

The latest patches are applied to GCC, Binutils and Newlib sources.

ABOUT GCC 4.9.2.201701-GNURL78

Release Version:	GCC 4.9.2.201701-GNURL78
Release Date:	1 st of April, 2017
Platforms Supported:	Red Hat GNU/Linux v8.0 or later (or compatible distribution) Windows XP, Windows 7, Windows 8, Windows 10
Language:	C, C99, C++
Targets:	G1X, I1X, D1X, LIN MCP, F1X, and L1X
Object File Format:	ELF

CHANGES IN GCC 4.9.2.201701-GNURL78

This section describes the fixes made in the GCC 4.9.2.201701-GNURL78 release.

GCC/Binutils:

- 1. [Improvement] New peephole optimization: use 16-bit moves instead of certain pairs of 8-bit moves (code size and speed improvement)
- 2. [Improvement] New RTL patterns for logical operations ("cstoreqi4" and "cstorehi4"), bit manipulation ("insvmisalign_qi"), switch statements ("casesi"), 8-bit arithmetic operations ("udivqi3" and "umodqi3")
- 3. [Improvement] Improved SFR addressing (code size reduction)
- 4. [Improvement] Linker relaxation enabled by default when optimizing for size (-Os) lead to improved section discarding (sensible code & data size reduction for some executables)
- 5. [Improvement] Smaller memory footprint of the libgcc library
- 6. [Improvement] Removed limitation requiring the use of the obsolete 8.3 naming convention for files in libgen
- 7. [Improvement] Added snprintf support for Optlib
- 8. [Bug-Fix] Fixed a rare case when a function argument was overwritten on the stack when optimizing for size (-Os)
- 9. [Bug-Fix] Fixed an internal error happening when performing a 32-bit right shift on a __far function Argument
- 10. [Bug-Fix] Fixed a couple of multiplication-related primitives that returned incorrect results on G13 MCUs

INSTALLER and RPM:

- 1. The GCC 4.9.2.201701-GNURL78 Installer onwards supports the 'Custom Installation' and 'Default Installation' modes. The 'Default Installation' mode is set by default where the tools are installed into the default location at "C:\Program Files\GCC 4.9.2.201701-GNURL78" and the user's username and activation key are silently accepted if cached in the registry.
- 2. The GNURL78 ABI (Application Binary Interface) is made available on our GNU Tools support website (https://gcc-renesas.com) and also provided along with Linux RPM and Windows installer.

Notes:

This installer does not provide an option to integrate the GNURL78 toolchain with e2 studio, as the e2 studio IDE will automatically detect the GNURL78 toolchain installation on start-up for integration. Alternatively, you may use the 'Toolchain Management' feature in e2 studio to achieve this.

For details on e2 studio please visit the following link below: http://www.renesas.com/products/tools/ide/ide_e2studio/index.jsp

There is no support in this installer to integrate toolchain with the HEW IDE.



KNOWN ISSUES IN GCC 4.9.2.201701-GNURL78

This section describes the known issues in the GCC 4.9.2.201701-GNURL78 release.

1. Following is a list of options and their combinations which can cause the Linker to fail:

- a) -the-fsignaling-nans (with -fno-inline -fno-trapping-math)
- b) -fno-tree-pre option (with -O2)
- c) -fno-tree-forwprop (with -O1)
- d) -fno-tree-dominator-opts (with -O2 -ffast-math)
- e) -fno-strict-aliasing option
- f) -fno-signed-zeros
- g) -fno-inline (with -fno-cse-follow-jumps)

All these options need adddition of the -DSTACK_SIZE=4096 flag.

Other known problems that may occur:

- 1. Linker error is observed when generating a program for RL78/G13 (S2 core), respectively RL78/G14 (S3 code), without using the specific G13/G14 multiply operations.
- a) The above described behavior can be recreated by compiling a C source files with the following option: "-Os -mcpu=g14 -mmul=none"
 - b) Note: the test file should attempt multiplying using a volatile variable.



FREE SUPPORT FOR GCC 4.9.2.201701-GNURL78

For free technical support, please register at https://gcc-renesas.com

For your feedback and suggestions, please visit https://gcc-renesas.com/help/contact-us/

