Release Notes: GCC 4.9.2.201703-GNURL78

2nd of October, 2017

CyberThor Studios Ltd. is releasing the GCC 4.9.2.201703-GNURL78, a cross compiler tool for Renesas RL78 micro-controllers.

SALIENT FEATURES

The GCC 4.9.2.201703-GNURL78 toolchain is based on:

- ❖ GCC 4.9.2 [released]
- ❖ Binutils 2.24 [released]
- Newlib 2.2.0 [released]
- ❖ GDB 7.8.2 [released]

The latest patches are applied to GCC, Binutils and Newlib sources.

ABOUT GCC 4.9.2.201703-GNURL78

Release Version:	GCC 4.9.2.201703-GNURL78
Release Date:	2 nd of October, 2017
Platforms Supported:	Red Hat GNU/Linux v8.0 or later (or compatible distribution) Windows XP or later
Language:	C, C99, C++
Targets:	G1X, I1X, D1X, LIN MCP, F1X, and L1X
Object File Format:	ELF

CHANGES IN THE GCC 4.9.2.201703-GNURL78

This section describes the fixes made in the GCC 4.9.2.201703-GNURL78 release.

GCC/Binutils:

- 1. [Improvement] New register allocator has been added to RL78 target (-mrl78reg-alloc)
- 2. [Improvement] objdump improved to display the multiplication/division registers by their name instead of their memory-mapped addresses.
- 3. [Improvement] The following patterns were added for G10, G13 and G14 cores udivmodqi4, udivhi3, umodhi3, udivmodhi4, divhi3, modhi3, divmodhi4, udivsi3, umodsi3, divsi3, modsi3
- 4. [Improvement] Stack protector has been added for the RL78 target.
- 5. [Improvement] Implemented aliases for -mcpu=g10,g13,g14 to resemble the manual (s1,s2,s3)
- 6. [Improvement] Implemented MOVE_BY_PIECES_P, SET_BY_PIECES_P and STORE_BY_PIECES_P for better code size.
- 7. [Bug Fix] Fixed the generation of "es:" before the sfr address.
- 8. [Bug Fix] Fixed:
 - mov [de],#IMM is interpreted now as mov [de+0],#IMM mov [hl],#IMM is interpreted now as mov [hl+0],#IMM
- 9. [Bug Fix] Fixed the behavior of lo16, hi16, hi8 local symbols to resemble lo16, hi16, hi8 global symbols
- 10. [Bug Fix] Fixed the precision error on floating-point addition.
- 11. [Bug Fix] Fixed compile error on accessing sfr with __far pointer.
- 12. [Bug Fix] Stack pointer arithmetic operations prohibited from modifying CPU flags
- 13. [Bug Fix] Corrected updating of the debug information when using new register allocator.
- 14. [Bug Fix] Corrected the save/restore of multiply registers in interrupts.
- 15. Optimized libgcc signed/unsigned div/mod

INSTALLER and RPM:

❖ The GCC 4.9.2.201703-GNURL78 Installer onwards supports the 'Custom Installation' and 'Default Installation' modes. The 'Default Installation' mode is set by default where the tools are installed into the default location at "C:\Program Files\GCC 4.9.2.201703-GNURL78" and the user's username and activation key are silently accepted if cached in the registry.

Notes:

This installer does not provide an option to integrate the GNURL78 toolchain with e2 studio, as the e2 studio IDE will automatically detect the GNURL78 toolchain installation on start-up for integration. Alternatively, you may use the 'Toolchain Management' feature in e2 studio to achieve this.

For details on e2 studio please visit the following link below: http://www.renesas.com/products/tools/ide/ide e2studio/index.jsp

There is no support in this installer to integrate toolchain with the HEW IDE.



KNOWN ISSUES IN GCC 4.9.2.201703-GNURL78

This section describes all known issues for this particular release:

1. GDB Issue - Stepover behaves as Stepin on certain function calls. The problem is present on -00 optimization due to adjustments to the stack (add/sub).



FREE SUPPORT FOR GCC 4.9.2.201703-GNURL78

For free technical support, please register at https://gcc-renesas.com

For your feedback and suggestions, please visit https://gcc-renesas.com/help/contact-us/

