LLVM for Renesas RL78 17.0.1.202506

Release Notes

30th of June, 2025

About LLVM for Renesas RL78 17.0.1.202506

CyberThor Studios Ltd. is releasing the LLVM for Renesas RL78 17.0.1.202506, a cross compiler tool for Renesas RL78 micro-controllers.

Release Version: LLVM for Renesas RL78 17.0.1.202506

Release Date: 30th of June, 2025

Platforms Supported:

- Ubuntu 20.04 or later (or compatible distribution)

- Windows 7 or later

- macOS Ventura 13.4 on Apple M1

Language: C, C++

Targets: All RL78 devices

Object File Format: ELF

The LLVM for Renesas RL78 17.0.1.202506 toolchain is based on:

- LLVM 17.0.1 [released]

- Compiler-rt 17.0.1 [released]

- Libcxx 17.0.1 [released]

- Libcxx-abi 17.0.1 [released]

- Newlib 4.3.0 [released]

- GDB 16.2 [released]

LLVM for Renesas RL78 comes with significant performance improvements (both code size and speed) compared to GCC RL78. It also comes with support for the latest language standards: full support for C17 and C++17 and partial support for C++20, C++23, C++2C.

The latest patches are applied to the LLVM sources.

Changes in LLVM for Renesas RL78 17.0.1.202506

This toolchain is the successor of GCC RL78 toolchain and it is meant as a direct replacement to GCC RL78.

This section describes the fixes made in the LLVM for Renesas RL78 17.0.1.202506 release.

1. **[Deprecation] -frenesas-vaarg**

The command line option *-frenesas-vaarg* was removed and it's functionality merged with the *-frenesas-extensions* option.

2. **[Deprecation] Removed 'R' inline assembly constraint**

The compiler selects whether to use the 8 or 16 bit register based on context, the usage of the R constraint for 8 bit registers is not required.

3. **[Deprecation] Removed VLA support**

Attempting to use variable length arrays will result in a compile error.

4. **[Change] mfar-data now implies mfar-rom too**

Using *-mfar-data* together with *-mfar-rom* when compiling C++ code could result in compile errors. This was fixed in the current release.

5. **[Change] Section alignment defaults**

The linker no longer sets the alignment for the *.callt0*, *.sbss*, *.dataf*, *.sdata*, *.bssf* and *.rodata* sections. The constraints were moved to the linker script, using explicit ALIGN(2) directives. Users are required to adapt custom linker scripts accordingly.

6. **[Change] Retain static interrupt functions**

The compiler no longer will discard static interrupt functions.

7. **[Improvement] Various codegen optimizations**

Code speed and size optimizations were made in the compiler.

8. **[Improvement] New option -minsert-nop-with-label**

The current release adds the *-mllvm -minsert-nop-with-label* option in order to support the Measuring Current Consumption feature in e2 studio. For details please consult the user manual.

9. **[Improvement] Support for .EXITM and .EXITMA assembler directive mixing with conditional assembly control**

The *.EXITM* and *.EXITMA* assembler directives are no longer restricted, they can be freely used with conditional assembly control directives.

10. **[Improvement] Implemented a more thorough pointer address space cast checking**

The detection of incompatible pointer address space conversions was improved in the current release.

11. **[Bug fix] Register save/restore issue in interrupts**

An issue that affected interrupt register saving and restoring was fixed in the current release.

12. **[Bug fix] Double precision multiplication issue**

A bug that may result in incorrect double precision multiplication when the operation is interrupted was fixed in the current release.

13. **[Bug fix] Function pointer with void comparison error**

A bug that resulted in the compiler crashing when comparing function pointers with *(void*)0* was fixed in the current release.

Notes

The toolchain on the Windows platform requires the presence of the x86 Microsoft Visual C++ Redistributable package for Visual Studio 2015-2022. This can be downloaded and installed from the official site: https://aka.ms/vs/17/release/vc_redist.x86.exe

This installer does not provide an option to integrate the LLVM RL78 toolchain with e2 studio, as the e2 studio

IDE will automatically detect the LLVM RL78 toolchain installation on start-up for integration. Alternatively, you may use the 'Toolchain Management' feature in e2 studio to achieve this.

For details on e2 studio, please visit the following link below: https://www.renesas.com/eu/en/software-tool/e-studio

There is no support in this installer to integrate the toolchain with the HEW IDE.

Known Issues in LLVM for Renesas RL78 17.0.1.202506

The following is a list of known issues for the tools included in the LLVM for Renesas RL78 17.0.1.202506 toolchain:

1. **Assembly parsing issue of 'callt' instruction operand**

   The assembly parser cannot handle any complex expressions as operands for the *callt* instruction, only constant values are allowed at the moment.

2. **Missing assembly listing support ('-a[cdhlns]' option in GNU AS)**

   There's no equivalent in LLVM for the *-a[cdhlns]* GNU AS option. The alternative solution is to use *llvm-objdump* to obtain source code interleaved with assembly (*-S, –source* option).

3. **Binding of references to packed fields**

   Creating references to struct members which are declared as packed, e.g., *__attribute__ ((packed))*, is incorrect as it can cause unaligned access issues. The compiler should return an error in this case, however, this is not currently the case. This will be fixed in a future release.

4. **Inline assembly missing constraints and modifiers support for parameters**

   Clang supports, in the case of RL78, inline assembly constructs without parameters, e.g., *asm (AssembleTemplate)*. The extended syntax available in GCC, *asm (AssemblerTemplate : OutputOperands : InputOperands : Clobbers : GotoLabels)*, is not currently supported. This will be fixed in the next release, however, the constraints will not be the same as in GCC.

5. **Far address space handling in C++ code**

   Currently, far data, far ROM, and far code handling in C++ are not supported.

6. **PLT usage for function calls over 64K**

   For each near call, where the callee was allocated over the 0xFFFF boundary, the linker will create an entry for the callee (if it doesn't exist yet) in the Procedure Linkage Table (PLT). The entry will consist of a *BR !!<Callee>* instruction, and the address written to the call instruction will be the address of the PLT entry. This indirection allows developers to increase the address range they can allocate their code, without the usage of *_far* functions.

   Example:

   test.c:

   ```
   void bar() __attribute__((section(".far_section")));
      void foo() {
         bar();
   }
   ```

   linkerscript.ld:

   ```
   ...
      .far_section 0x111D8 : AT(0x111D8)
      {
         . = ALIGN(2);
         *(.far_section)
         . = ALIGN(2);
      } >ROM
   ...
   ```

   will result in the following ELF file:

   ```
   ...
   000000d8 .lowtext:
      d8: ec d8 11 01         br !!_bar
      ...
   00003004 _foo:
   ```

```
   3004: fd d8 00          call !.lowtext
   3007: d7                ret
   ...
000111d8 _bar:
```

7. **clang: '"-save-temps -g"' option leads to "warning: inconsistent use of MD5 checksums"**

   See https://github.com/llvm/llvm-project/issues/56378

8. **Other issues, non-specific to RL78**

   LLVM tries to be a complete replacement. As such, there are still a couple of missing features from GCC which will be implemented in future releases. In particular, the following issues should be noted:

   - lld: Information printed using *–print-gc-sections* is not as nice as when using the GNU ld. [Bug 46783](https://bugs.llvm.org/show_bug.cgi?id=46783)

   - llvm-ar: Errors when printing multiple members with the same name. [Bug 42521](https://bugs.llvm.org/show_bug.cgi?id=42521)

   - llvm-dwarfdump: Does not print section attribute flags yet. [Bug 38488](https://bugs.llvm.org/show_bug.cgi?id=38488)

   - llvm-nm: Unable to understand symbols built with gcc-lto. [Bug 41437](https://bugs.llvm.org/show_bug.cgi?id=41437)

   - llvm-nm: Needs support for –line-numbers to llvm-nm. [Bug 40001](https://bugs.llvm.org/show_bug.cgi?id=40001)

   - llvm-objcopy: Unknown argument '–change-section-address'. [Bug 45217](https://bugs.llvm.org/show_bug.cgi?id=45217)

   - llvm-objcopy: Objcopy zero-size section might cause huge binaries. [Bug 46299](https://bugs.llvm.org/show_bug.cgi?id=46299)

   - llvm-objdump: Prints wrong line number info for obj file compiled with -ffunction-sections. [Bug 40703](https://bugs.llvm.org/show_bug.cgi?id=40703)

   - llvm-objdump: Wrong behavior for non-relocatable objects when suing llvm-objdump with -r option. [Bug 41901](https://bugs.llvm.org/show_bug.cgi?id=41901)

   - llvm-readobj: Make GNU style symbol printing invalid symbol section indexes match GNU readelf [Bug 43850](https://bugs.llvm.org/show_bug.cgi?id=43850)

   - llvm-readelf: Relocation addends printed style does not match GNU readelf [Bug 45235](https://bugs.llvm.org/show_bug.cgi?id=45235)

   - llvm-string: Short option with argument grouping not GNU compatible [Bug 42942](https://bugs.llvm.org/show_bug.cgi?id=42942)

   - llvm-string: Allow "-<integer>" as an alias for "-n <integer>" [Bug 42964](https://bugs.llvm.org/show_bug.cgi?id=42964)

   - llvm-symbolizer: Shows incorrect source line info if –gc-sections used [Bug 41124](https://bugs.llvm.org/show_bug.cgi?id=41124)

   - llvm-symbolizer: llvm-addr2line does not exit when passed a non-existent file [Bug 42754](https://bugs.llvm.org/show_bug.cgi?id=42754)

9. **Other issues**

   For better understanding regarding the status of the toolchain please visit https://github.com/llvm/llvm-project/issues

Free support for LLVM for Renesas RL78 17.0.1.202506

For free technical support, please register at https://llvm-gcc-renesas.com

For your feedback and suggestions, please visit https://llvm-gcc-renesas.com/help/contact-us/